

P.O. BOX 3090 ONE AYRES WAY ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Bulletin No. SB-AG-15 Page 1 of 3 April 24, 1979

## RUDDER UPPER HINGE INSPECTION

MODELS AFFECTED: Model S2-R, S/N 1416 thru 2439: S/N 5000 thru 5100.

REASON FOR PUBLICATION: Inspect for possible cracks in rudder upper hinge.

COMPLIANCE: Within 25 flight hours upon receipt of this service bulletin and every

100 hours there after up to 300 hours; then annually thereafter.

NOTE

IF ANY PROBLEMS ARE ENCOUNTERED WHILE COMPLYING WITH THIS SERVICE BULLETIN, CONTACT YOUR NEAREST AYRES THRUSH DEALER.

BY WHOM WORK WILL

BE ACCOMPLISHED: A & P Mechanic or equivalent

APPROVAL: FAA DER Approved

ESTIMATED MAN HOURS: Three (3) Hours

SPECIAL TOOLS: None

**INSTRUCTIONS:** 

- 1. Remove rudder assembly from airplane. Remove rudder as outlined in the AYRES THRUSH MAINTENANCE MANUAL, SECTION VII.
- 2. Strip fabric and dope from area around rudder hinge to facilitate inspection.

- 3. Inspect in and around weld bead on rudder hinge bushing for cracks. (See Figure 1).
- 4. If no cracks are found, proceed to Step 7.
- 5. If cracks are found, order replacement Rudder Part Number 54030-987 through the nearest Ayres Thrush Dealer and install per Section VII of the Maintenance Manual PRIOR TO FURTHER FLIGHT.
- 6. Fill out and mail Compliance Card noting rudder replaced.
- 7. Repaint and recover rudder assembly In area around hinge with new fabric in accordance with FAA Advisory Circular AC 43.13-1, Chapter 3.
- 8. Re-install rudder assembly per Section VII of the maintenance manual.
- 9. Fill out and mail Compliance Card noting that no cracks were found.

ELECTRICAL LOAD: NO CHANGE

WEIGHT AND BALANCE: NO CHANGE

AIRCRAFT RECORDS: Make appropriate entry in aircraft permanent records as follows:

Service Bulletin No. SB-AG-15, dated October 9, 1978, entitled "rudder Upper Hinge Inspection", accomplished \_\_\_\_\_\_\_.




Figure 1

Page 3 of 3



P.O. BOX 3090 ONE AYRES WAY ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Bulletin No. SB-AG-15 **Revision No. 1 April 24, 1979** 

## RUDDER UPPER HINGE INSPECTION

APPROVAL: FAA DER APPROVED.

**REVISE AS FOLLOWS:** 

Page 1 of 3 – MODELS AFFECTED

CHANGE TO: Model S2R-R, Serial Nos. 1416 thru 2439

Serial Nos. 5000 thru 5100

Models S2D, Serial Nos. 1311D thru 1415D