

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Letter No. SL-AG-97 1 October, 1982 Revised 23 August 1994

LOWER WING SPAR INSPECTION

MODELS AFFECTED: All S-2D, S-2R, S2R-T15, S2R-T34, S2R-R1820 AND S2R-

G10 operating in the Commonwealth of Australia

REASON FOR PUBLICATION: This Service Letter is being issued to provide for periodic

inspection of the lower wing spar assembly for fatigue

cracks.

COMPLIANCE:

1 For Models S2D and S2R, at 2500 hours time in service

and every 500 hours thereafter.

2 For Models S2R-T15 and S2R-T34, at 2500 hours time in

service and every 500 hours thereafter.

3 For Model S2R-R1820, at 2500 hours time in service and

every 500 hours thereafter.

4 For model S2R-G10, at 2500 hours time in service at

every 500 hours thereafter.

NOTE

IF ANY PROBLEMS ARE ENCOUNTERED WHILE

COMPLYING WITH THIS SERVICE LETTER. CONTACT

YOUR NEAREST AYRES THRUSH DEALER.

BY WHOM WORK WILL

BE ACCOMPLISHED: A & P mechanic or equivalent.

APPROVAL: Ayres Corporation, Engineering Department

ESTIMATED MAN HOURS: 3 to 4 man hours

PARTS DATA: None

> PAGE 1 of 6 SL-AG-97

SPECIAL TOOLS: None

DOCUMENT REFERENCE: AD/AC-Snow/14

ACCOMPLISHMENT INSTRUCTIONS:

- 1. Remove left and right belly skins located just aft of the firewall. These skins are located adjacent to the spray pump mount. This will provide access to the main spar center section.
- 2. Remove lower wing root fairings to provide access to the lower spar web flange.
- 3. Visually inspect the lower spar for fatigue cracks from the airplane centerline outboard to the wing root rib paying attention to the following: (See Figure 1 & 2)
 - a. Lower spar web flange P/N 20273
 - b. Lower half of forward doubler P/N 20230
 - c. Lower half of center splice plate P/N 20211 (aft side of spar assembly).
 - d. Lower half of doubler P/N 20271 which is located on the aft side of the spar assembly and terminates at the root rib.
 - e. Inspect each huck pin head and collar for signs of looseness or evidence that the pins are "working". Check for cracks radiating from under the huck pin head or collar.
 - f. Inspect all bolt heads and nuts for looseness or cracks radiating from them.
 - g. Outboard of the root rib along with lower spar to leading edge attachments, check for loose rivets, cracked leading edge skin or cracks from under the rivet heads.
- 4. If cracks are found, remove wing from aircraft and replace the cracked part using established, standard aircraft practices.
- 5. Fill out enclosed compliance card indicating the results of the inspection noting which part was replaced.
- 6. Return the aircraft to service.
- 7. If no cracks are found, fill out enclosed compliance card so indicating.
- 8. Return the aircraft to service.

ELECTRICAL LOAD: No change

WEIGHT & BALANCE: No change

PUBLICATIONS


AFFECTED: NONE

PAGE 2 of 6 SL-AG-97

RECORD COMPLIANCE:

Make appropriate entry in aircraft maintenance records as follows: Service Letter NO. SL-AG-97 dated October 1, 1982, entitled "Lower Wing Spar Inspection" accomplished (date) .

PAGE 3 of 6 SL-AG-97



COMPLIANCE CARD SERVICE LETTER SL—AG—97 S/NOWNER		
DEFECTS	NO DEFECTS	
INSPECT'D BY		DATE