

Rockwell service letter No. SL-AG-76

International

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Letter No. SL-AG-76
30 January, 1976

CARBURETOR REPLACEMENT

MODELS AFFECTED: MODEL S-2R, S/N 5000 thru 5082.

REASON FOR PUBLICATION: Assure constant fuel consumption.

COMPLIANCE: At Owner's Discretion.

BY WHOM WORK WILL BE ACCOMPLISHED: A & P Mechanic or equivalent

APPROVAL: FAA DER Approved

ESTIMATED MAN HOURS: Six (6) Hours

PARTS DATA: Parts required to comply with this Service Letter are furnished as a kit, at no charge, by Rockwell International, General Aviation Division, Albany, Georgia, 31702 and consist of the following:

Qty	Part No.	Description
1 ea.	148858	Gasket
1 ea.	390199-9	Carburetor (identified w/a green stripe painted on the brace plate).
1 ea	Service Letter SL-AG-77	Instructions
1 ea		Compliance Card

SPECIAL TOOLS: None

ACCOMPLISHMENT INSTRUCTIONS:

1. Remove engine cowling as necessary to gain access to carburetor.
2. Remove existing carburetor and install 391099-9 carburetor and 148858 gasket as outlined in the Airplane Maintenance Manual, Section IV.
3. Record engine and carburetor serial numbers on enclosed Compliance Card and on airplane maintenance records.
4. Reinstall engine cowling.
5. Fill out and mail Compliance Card.

ELECTRICAL LOAD: No Change

WEIGHT AND BALANCE: No Change

PUBLICATIONS AFFECTED: NONE.

RECORD COMPLIANCE: Make appropriate entry in airplane maintenance records as follows:

Service Letter No. SL-AG-76 dated 30 January 1976, entitled "Carburetor Replacement", accomplished (date)_____.