

# Rockwell service letter No. SL-AG-6

## International

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

---

---

Service Letter No. SL-AG-6  
May 24, 1961

### ELEVATOR PULLEY INSTALLATION

#### Service Letter #6

**SERIAL NO:** 1005 and Subs.

**APPLICABILITY:** All S-2A aircraft through Serial Number 1093A

The enclosed instructions are for installation of the AN210-4B pulley mentioned in Service Letter #4. This pulley will replace the AN210-23B pulley presently in the system. A kit is provided to adapt the brackets for the installation of the larger pulley.

The kit is FAA approved and should provide a satisfactory solution to any elevator cable wear problems previously experienced.

Engineering Department

Enclosure:

1. Instructions
2. Kit List