

International

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Letter No. SL-AG-21
27 November, 1962

AILERON STOP CABLE

APPLICABILITY: S-2B aircraft 1003 through 1096-B

A report has been received of the aileron stop cable wrapping around the turn buckle eye during flight and seriously restricting the aileron travel.

It is suggested that the turnbuckles be removed and 3/32" 7 x 19 stop cable be extended to attach to the structure.

The length of this cable should be such that proper aileron travel is maintained.

Engineering Department