

# Rockwell service bulletin No. SB-AG-3

## International

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

**Service Bulletin No. SB-AG-3**  
**April 23, 1974**

### SEAT CUSHION REPLACEMENT

EFFECTIVITY: MODEL S-2R, SERIAL NO'S 1807 THRU 1899.

COMPLIANCE: WITHIN NEXT TEN (10) FLIGHT HOURS.

APPROVAL: FAA DER Approved.

PURPOSE: To help improve pilot's visibility with higher seat cushion.

#### INSTRUCTIONS:

- a. Remove and discard existing seat back assembly and seat bottom assembly.
- b. Install 11172-1 seat bottom assembly and 11172-3 seat back assembly.

#### SUPPLY DATA:

The following parts required to comply with this Service Bulletin may be obtained, at no charge, from your nearest Thrush Commander Distributor.

QTY	PART NO.	DESCRIPTION
1 ea.	11172-1	Seat Bottom Assy
1 ea.	11172-3	Seat Back Assy

ELECTRICAL LOAD: Not Applicable.

WEIGHT AND BALANCE: Not Applicable

AIRCRAFT RECORDS: Make appropriate entry in aircraft permanent maintenance records as follows:  
Service Bulletin No. SB-AG-3, dated April 23, 1974, entitled "Seat Cushion Replacement", accomplished \_\_\_\_\_ (dated)\_\_\_\_\_.