

# SERVICE LETTER

## SL-AG-133

Initial Release: 03/21/2024

## ALL S2R MODELS

## Aileron Bell Crank Support Tubes Inspection

Affected Aircraft Models	Serial Number Range
S2R	ALL

David Yarbrough Director of Engineering



## TABLE OF CONTENTS

4.	COMPLIANCE	7
	3.3 REPORT	.6
	3.2 INSPECTION	.5
	3.1 HOW TO ACCESS	4
3.	INSTRUCTIONS	4
2.	SCOPE/COMPLIANCE	.4
1.	PURPOSE/REASON FOR PUBLICATION	.4



## LOG OF REVISIONS

**NOTE:** Reformatting and correction of typographical errors is not considered revision. True revisions are indicated by a dark vertical line at the right margin of the lines revised.

Rev.	Page	Description of Revision	By:
IR	All	New Document Initial Release.	T. Surratt 03/21/2024



### 1. PURPOSE/REASON FOR PUBLICATION

Thrush has been notified by one or more operator(s) of a crack that has developed on the aileron bell crank support tubes after hours of flight.

This Service Letter acts as an Inspection Notification to ALL S2R model aircraft operators of the possibility of a crack on the aileron bell crank support tubes.

### 2. SCOPE/COMPLIANCE

This Service Letter contains the instructions for the inspection of the aileron bell crank support tubes for the possibility of a crack.

#### **3. INSTRUCTIONS**

#### 3.1 HOW TO ACCESS

 Remove panel from right-hand (RH) side of aircraft, located below cockpit and above aft wing fairing.



Figure 3.1.1





Figure 3.1.2

#### **3.2 INSPECTION**

• Visually inspect both aileron bell crank support tubes entirely, especially each weld joint.



Figure 3.1.3





Figure 3.1.4

#### 3.3 REPORT

 If cracks or any other damage is found, please send an email to <u>support@thrushaircraft.com</u>. Also, please fill out and return the Compliance Report, located on the next page.



### 4. COMPLIANCE

#### Service Letter SL-AG-133 Rev. IR Compliance Report

Aircraft S/N:	Aircraft Owner:	
Aircraft Registration #:	Address of Owner:	
Airframe Total Time:	City & State:	
Engine Total Time:	Physical Location:	
Complied With By:	Date of Compliance:	
Signature:	Certificate #:	

#### PLEASE RETURN THIS REPORT ONLY AFTER INSPECTION IS MADE

This response card may be mailed, faxed to (229) 317-8225, or emailed to: <u>support@thrushaircraft.com</u>.

Fold, Tape & Mail (Do Not Staple)

Return Address:

Thrush Aircraft LLC. Attn: Customer Support Team 300 Old Pretoria Road Albany, Ga 31721