

Rockwell service letter No. SL-AG-80

International

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Letter No. SL-AG-80
Revision No. 1
12 April, 1976

CRANKCASE AIR/OIL SEPARATOR INSTALLATION

APPROVAL: FAA DER Approved

Page 1 of 5 - Parts List:

Change:	Part No:	Was: 1 ea	60147-15	Tube Assy
		Now: 1 ea	60147-19 or 60147-15	Tube Assy
		Was: 1 ea	16C50X	Elbow
		Now: 1 ea	16C50X or AN822-16	Elbow
		Was: 1 ea	159-47162 or AN775-12	Bolt
		Now: 1 ea	159-47162 or 60611-RE1	Bolt

ACCOMPLISHMENT INSTRUCTIONS:

Change: Step 9 to read:

9. After oil has stopped draining, install AN776-12 universal, AN900-16 gasket, AN900-17 gasket, and 159-47162 or 60611-RE1 bolt in supercharger drain hole (see Figure 1).

Step 12 to read:

12. Install 16C50X or AN833-16 elbow and 60147-19 or 60147-15 tube assembly (see Figure 1).

NOTE

Install 16C50X elbow when using 60147-19 tube assembly and AN833-16 elbow when using 60147-15 tube assembly.

Page 4 of 5:

Change: Figure 1 (sheet 2 of 3) as shown on page 2 of this revision.

AFTER CHANGE

