

Aero Commander service letter No. SL-AG-10

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Letter No. SL-AG-10
12 June, 1961

MARLEX FAIRLEAD AVAILABILITY

APPLICABILITY: All "A" and "B" Models through S/N 1062

This letter is a reminder of the availability of the Marlex fairleads for installation. You should have received a telegram earlier concerning the inspection of the control system and the availability of the Marlex fairleads. It is strongly recommended that any other type fairleads be replaced with Marlex fairleads throughout the system.

Your prompt return of the enclosed self addressed card will be a valuable aid in keeping our aircraft status records current at the plant.

Engineering Department.

Service Letter No. 10

S-2A and S-2B Serial Number _____.

- 1 No Marlex fairleads have been installed (_____).
- 2 Marlex fairleads have been installed as follows:

| System | Aileron | Rudder | Elevator |
|---------------|-----------|-----------|-----------|
| No. In System | 8 | 8 | 2 |
| No. Installed | (_____) | (_____) | (_____) |
- 3 Please send me (_____) Marlex fairleads (should order enough for the complete system - - - cost - \$0.32 each). Price may change.
- 4 I have () have not () installed aileron push-pull system in the above aircraft.

Signed: _____.