

Rockwell service letter No. SL-AG-24

International

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Letter No. SL-AG-24
April 12, 1963

REAR PROP CONE

APPLICABILITY: All S-2A Aircraft, Serial Number 1005 & UP

It has been brought to our attention that there is the possibility that the wrong type of rear prop cone may be installed on some of the S-2A's in service.

Investigation has shown that two types of rear cones were produced for use with the McCauley propeller and for some unexplainable reason, the same part number was used for both types.

It is suggested that the rear prop cone be checked immediately to see if it is the proper type.

This may be done without removing the propeller. With a pair of calipers, measure the outside diameter of the rear cone. The right type should measure 3 1/8". The wrong type will measure 2 15/16".

All cones have been furnished by Gulf Coast Dusting Company of Houston. Therefore, it is suggested that you contact them for the proper type.

Their address is:

Gulf Coast Dusting Company
Route #7, Box 1172-A
Houston, Texas