

Rockwell service letter **No. SL-AG-49**

International

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Letter No. SL-AG-49
August 25, 1967

P/N 10852-1 FIRE EXTINGUISHER PLACARD INSTALLATION

APPLICABILITY: ALL 600 S-2D Aircraft, Serial Number 1311D through 1415D.

Model 600 S-2D owners that have factory furnished fire extinguishers installed. The Federal Aviation Agency advises that a placard, cautioning the pilot against use of the fire extinguisher while in flight, must be installed on the fire extinguisher so that pilot can read the placard.

Placard to be installed on fire extinguisher.

Subject placard is being forwarded at no charge under separate cover to all S-2R owners who have factory installed fire extinguishers in their aircraft.