

custom kit

No. CK-AG-25

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Custom Kit CK-AG-25
13 October, 1992

GENERATOR FAILURE WARNING LIGHT KIT

MODELS AFFECTED: Model S-2R, All Serial Numbers, with AN3025-1 Reverse Current Relay

REASON FOR PUBLICATION: This publication has been written to comply with United Kingdom CAA Airworthiness Notice No. 88, Issue 2, 17 March 1992. This kit will provide operators with the drawings and parts required to give the pilot a clear and unmistakable visual warning that the generator is no longer supplying the electrical needs of the airplane, and that the battery's electrical energy depletion is imminent.

COMPLIANCE: In accordance with CAA Airworthiness Notice No. 88 Issue 2.

BY WHOM WORK WILL BE ACCOMPLISHED: Any properly certificated Aircraft Mechanic.

APPROVAL: FAA Approved

ESTIMATED MAN HOURS: 3

PARTS DATA: Parts to comply with this kit are listed on Drawing Number CK-AG-25 and are available from Ayres Corporation.

ACCOMPLISHMENT INSTRUCTIONS: Are on Drawing CK-AG-25

WEIGHT AND BALANCE: Negligible, no change required.

RECORD COMPLIANCE: Make appropriate entry in airplane maintenance records as follows:
Custom Kit NO. CK-AG-25 dated October 13, 1992, entitled "Generator Failure Warning Light Kit", accomplished (date) _____, by (name) _____.