

Rockwell service letter

International **No. SL-AG-91**

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Letter No. SL-AG-91
Revision No. 1
25 August, 1977

BRAKE MASTER CYLINDER REPLACEMENT

APPROVAL: FAA DER Approved

Page 1 of 2 – Models Affected:

Change to read: S2R S/N 1939R thru 2240R and 5000R thru 5082R with MIL-H-5606 red oil system.